Bangladesh Navy Hydrographic and Oceanographic Centre New Mooring, Chattogram www.bnhoc.navy.mil.bd

Mobile: 01769722420 E-mail: bnhoc@navy.mil.bd

02 Poush 1432

23.02.1528.913.55.157.25.12 13

i December 2025

# **BNHOC NOTICE NO 42/2025**

#### References:

- Payra Port Authority letter no 18.21.7866.000.014.92.001.23.90 dated 11 December 2025 (Not to all). BNHOC Notice No 05(T)/2025 dated 02 March 2025.
- B.
- 1. Following Permanent Notice to Mariners is hereby promulgated:

#### **Delete**

Delete	Position	Charts Affected	Datum	
<>	21°43.62′N, 090°16.31′E to 21°51.83′N, 090°16.19′E	BN 3002 (INT 7453), BN 3521 and BN 7504 (INT 7454)	Distribut Externaci	
Dredged Channel (See Note)	21°44.32′N,090°16.51′E		nolioA	
Dredged to 9.3m (2020)	21°48.36′N, 090°16.18′E and 21°44.50′N, 090°16.23′E	BN 3521	WGS 84	
Dredged Channel (See Note)	21°49.26′N, 090°16.16′E	BN 3002 (INT 7453)		
Dredged to 9.3m (2024)	21°49.22′N, 090°16.33′E	enne sycobon se en		
Dredged to 9.3m (2024)	21°47.34′N, 090°16.14′E	BN 7504 (INT 7454)		

### Insert

Insert.	Position	Charts Affected	Datum
Dredged to 9.3m (2024)	024) 21°52.94′N, 090°16.66′E		
Dredged Channel (See Note)	21°37.94′N, 090°13.58′E	BN 3521	WGS 84
Dredged to 9.3m (2024)	21°52.70′N, 090°16.66′E	BN 7504 (INT 7454)	roomma0

Delete	Contract of	LFI.G.6s No-21	21° 46′.67N, 90° 16′.37E
		No-21	Constander Suberstane
	₽ R	LFI.R.6s No-22	21° 46′.67N, 90° 16′.18E.
	•	LFI.G.6s No-23	21° 49'.67N, 90° 16'.32E
			Citatorian, Mongia Port Authorau
	R	LFI.R.6s No-24	21° 49'.66N, 90° 16'.14E.
Insert	G	LFI.G.6s No-21	21° 45′.419N, 90° 16′.128E.
	R	LFI.R.6s No-22	21° 45′.399N, 90° 15′.954E.
	is a feeting		Participal Orders Marchaele Margine Office - By Francis
	6	LFI.G.6s No-23	21° 49'.689N, 90° 15'.752E.
	R	LFI.R.6s No-24	21° 49'.676N, 90° 15'.579E.
		102.00	That Clares a visuation layer more make in time

Move

6

LFI.G.65

From:

21° 43'.17N, 90° 16'.18E

to:

21° 43'.167N, 90° 16'.181E.

R LFI.R.6s No-20 From:

21° 44'.11N, 90° 16'.22E

to:

21° 44'.084N, 90° 16'.070E.

## Charts affected: BN 3002 (INT 7453), BN 3521, BN 7504 (INT 7454) [WGS84 DATUM]

2. All ships are requested to incorporate necessary corrections on the above-mentioned charts and navigate in the waterway marked by the above mentioned buoys.

3. BNHOC Notice No 05(T)/2025 be treated as cancel.

ARIFUR RAHMAN

Captain BN

**Commanding Officer** 

Distribution:

External:

Action:

**BN** Chief Hydrographer

- With request to circulate among the ships under your command.

Information (Not as per seniority):

**Directorate of Naval Operations** 

- By E-mail.

Directorate of Hydrography

Commander Khulna Naval Area

Commander BN Fleet

Commander Chattogram Naval Area

Commander Dhaka Naval Area

Commodore Naval Aviation

Commodore SWADS Command

Commander Submarine

Commander Flotilla West

Coast Guard Headquarters Directorate of Operations

Chairman, Mongla Port Authority

Chairman, Chattogram Port Authority

Chairman, Payra Port Authority

Managing Director

Bangladesh Shipping Corporation

Principal Officer, Mercantile Marine Office

Joint Director, BIWTA, Khulna

Deputy General Manager, BIWTC, Khulna

The United Kingdom Hydrographic Office

 By E-mail(With request to circulate among the ships/ units under respective command).

By E-mail.

- By E-mail (With request to circulate among the maritime organizations/agencies).

- By E-mail.