

23.02.1528.340.55.157.19. 173

12-Mar 19
















**BNHOC NOTICE NO 15/2019**

Refs:

- A. BIWTA Ltr no 18.810.004.01.00.030/4,2011/421 dated 20 Feb 2019 (Notal).  
B. BIWTA Notice no 05/2019 dated 18 Feb 2019 (Notal).


1. Following **PERMANENT** corrections are to be applied:

**Charts affected - BN 7509, BN 3511, BN 7510 (INT 7428), BN 25002, BN 35001 (INT 7425), (WGS84 DATUM)**

Delete		Fl.G.6s Authority Buoy	22° 16' .35N 091°35' .59E
Insert		LFl.G.6s Authority Buoy	22° 12' .26N 091°38' .62E
Delete		Fl (2)G.6s	22° 14' .31N 091°38' .40E
Delete		Fl (2)G.6s	22° 14' .58N 091°38' .29E
Delete		Fl.R.6s SS Buoy	22° 17' .85N 091°33' .75E
Delete		Fl.G.5s WS Buoy	22° 21' .62N 091°29' .11E
Delete		Fl.W Bhasan Char-1	22° 18' .16N 091°27' .91E
Insert		LFl.G.6s Bhasan Char-1	22° 08' .58N 091°27' .27E
Delete		Fl.W Bhasan Char-2	22° 18' .55N 091°23' .18E
Insert		LFl.R.6s Bhasan Char-2	22° 09' .04N 091°25' .06E
Insert		LFl.R.6s Hatia-1	22° 12' .12N 091°19' .28E
Insert		LFl.G.6s Hatia-2	22° 19' .09N 091°13' .28E
Insert		LFl.R.6s	22° 25' .90N 091°07' .98E
Insert		LFl.R.6s	22° 29' .99N 091°03' .60E
Insert		LFl.G.6s Lambur Hat	22° 30' .31N 091°01' .68E

RESTRICTED

2. All ships are requested to incorporate necessary correction on above-mentioned charts and navigate accordingly.

  
N U NAHAR  
Instr Lt Cdr BN  
For Officer in Charge  
(Absent on TY Duty)

Distr:  
Extl:  
Act:

The Commanding Officer/Officer-in-Charge  
BNS/BNT -----

(All ships/crafts under COMCHIT)

Info:

Dte of Naval Operations

Dte of Hydrography

Commander Chattogram Naval Area

Commander Khulna Naval Area

Commander Submarine

Commander BN Fleet

Commodore Naval Aviation

Administrative Authority Dhaka

Commodore SWADS Command

COMFLOT West

CG Force Headquarters, Dte of Operations  
Agargaon Admin Area, Sher-e-Bangla Nagar,  
Dhaka 1207

Chairman, Chattogram Port Authority

Chairman, Payra Port Authority  
Al-Amin Millennium Tower (7 Level)  
75-76 Kakrail, Dhaka - 1000

Chairman, Mongla Port Authority

Principal Officer, Mercantile Maine Office  
CGO Building, Agrabad, Chattogram

Managing Director  
Bangladesh Shipping Corporation  
BSC Bhaban, Chattogram

Deputy Conservator  
Chattogram Port Authority, Chattogram

Joint Director, BIWTA  
Terminal Bhaban, Feringhee Bazar  
Bridge Ghat Chattogram

Deputy General Manager, BIWTC  
Sadarghat, Chattogram

The United Kingdom Hydrographic Office  
Admiralty Way, Taunton, Somerset  
TA1 2DN, United Kingdom.

With request to circulate to ships under  
respective Command/Org

With request to circulate to ships under  
respective Command/Org

- By E-mail.