

Bangladesh Navy  
Hydrographic and Oceanographic Centre  
New Mooring, Chattogram  
www.bnhoc.navy.mil.bd

Tel: 740391-9 ext 2450  
E-mail: bnhoc@navy.mil.bd

23.02.1528.913.55.157.21. 199

15 15 February 2021

**BNHOC NOTICE NO 08/2021**

References:

- A. MPA letter no 18.14.0158.312.36.011. (Aw -1).21-380-1 dated 03 January 2021(Not to all).
- B. MPA circular no 11/2021 dated 31 January 2021(Not to all).
- C. MPA E-mail dated 03 February 2021(Not to all).

1. Following Notice to Mariners is hereby promulgated:

**Insert**

 FI(3)R.12s B-2	21° 27'.92N, 89° 30'.64E
 FI(2)G.12s B-7	21° 33'.88N, 89° 28'.70E
 FI(2)R.12s B-8	21° 33'.88N, 89° 27'.00E
 FI(3)G.15s B-9	21° 35'.98N, 89° 29'.53E
 FI(3)R.15s B-10	21° 35'.93N, 89° 26'.93E
 FI(2)G.12s B-11	21° 38'.42N, 89° 28'.31E
 FI(2)R.12s B-12	21° 38'.42N, 89° 26'.96E
 FI.G.8s B-13	21° 40'.05N, 89° 28'.63E
 FI.R.8s B-14	21° 40'.05N, 89° 27'.56E
 FI(4)G.15s B-15	21° 42'.09N, 89° 29'.08E
 FI(4)R.15s B-16	21° 42'.09N, 89° 28'.14E
 FI(2)G.10s B-17	21° 44'.12N, 89° 28'.94E
 FI(2)R.10s B-18	21° 44'.12N, 89° 28'.12E
 FI.G.6s B-19	21° 46'.15N, 89° 29'.14E

**Insert**

	Fl.R.6s B-20	21° 46'.15N, 89° 28'.27E
	Fl(2)R.10s B-22	21° 47'.38N, 89° 28'.63E
	Fl(3)R.15s B-24	21° 48'.32N, 89° 29'.81E
	Fl(4)R.20s B-26	21° 49'.24N, 89° 30'.65E
	Fl(2)G.12s BB-1	21° 38'.06N, 89° 30'.20E
	Fl.G.8s BB-3	21° 39'.64N, 89° 31'.05E
	Fl.R.8s BB-4	21° 39'.23N, 89° 29'.94E
	Fl.10s NK Buoy.	21° 49'.03N, 89° 28'.75E

**Delete**

	Fl(2)R.12s B-8	21° 34'.38N, 89° 27'.17E
	Fl(3)G.20s B-9	21° 35'.87N, 89° 29'.12E
	Fl.R.8s B-10	21° 36'.34N, 89° 27'.90E
	Fl(2)G.10s B-11	21° 38'.01N, 89° 30'.31E
	Fl(2)R.10s B-12	21° 38'.00N, 89° 28'.96E
	Fl.G.6s B-13	21° 40'.04N, 89° 31'.15E
	Fl.R.6s B-14	21° 40'.04N, 89° 30'.25E
	Fl(3)G.20s B-19	21° 46'.52N, 89° 31'.38E
	Fl.10s Nil Kamal	21° 48'.82N, 89° 28'.78E

**Amend**

light- buoy to, LFl.10s	21° 26'.86N, 89° 33'.97E
light to, FL(2).10s36m20M	21° 47'.83N, 89° 28'.37E
light to, FL(2).10s40m20M	21° 45'.40N, 89° 32'.80E

