Bangladesh Navy Hydrographic and Oceanographic Centre New Mooring, Chattogram www.bnhoc.navy.mil.bd

Tel: 02333342500-30 ext 2450 E-mail: bnhoc@navy.mil.bd

19 Choitro 1429

0 2 April 2023

23.02.1528.913.55.157.23. 293

## **BNHOC NOTICE NO 05/2023**

## References:

- A. BNHOC notice no 18/2012 dated 23 July 2012.
- B. BNHOC notice no 33(T)/2016 dated 20 December 2016.
- C. BNHOC notice no 04/2017 dated 18 January 2017.
- D. BNHOC notice no 01/2018 Dated 01 February 2018.
- E. BNHOC notice no 32(T)/2019 dated 08 August 2019.
- F. BNHOC notice no 01(T)/2020 dated 16 January 2020.
- G. BNHOC notice no 11(T)/2020 dated 16 July 2020.
- H. BNHOC notice no 07/2021 dated 08 February 2021.
- J. BNS SHAIBAL letter no 23.02.1528.431.37.165.21.1012 Dated 11 August 2021 (Not to all).
- K. BNS SHAIBAL letter no 23.02.1528.431.37.165.22.288 dated 30 April 2022 (Not to all).
- L. BNS DARSHAK letter no 23.02.1528.327.30.020.22.76 dated 05 April 2022 (Not to all).

## 1. Following Permanent Notice to Mariners is hereby promulgated:

Delete	*	21° 47′.09N., 91° 30′.49E.
	<del>(  )</del>	21° 42′.37N., 90° 58′.17E.
	<del>(  )</del>	22° 12'.91N., 91° 47'.99E.
	PA PA	22° 10′.00N., 91° 49′.25E.
	a best grown	21° 45′.91N., 91°29′.46E.
	*	22° 11′.31N., 91°48′.90E.
	<b>⊕</b> PA	22° 05′.70N., 91°31′.43E.
Insert	<del>(ii)</del>	21° 47'.14N., 91° 30'.52E.
	Obstn	21° 41′.79N., 90° 58′.05E.
	(4 <sub>6</sub> ) Wk	22° 12'.599N., 91° 48'.001E.
	<del>(  )</del>	21° 45′.76N., 91°29′.36E.
	<del>(  )</del>	22° 05′.81N., 91°31′.48E .

Move	fror	m: 21° 49′.70N.,	91°29′.20E.
	wan panna www - t	o: 21° 49′.90N.,	91°29′.22E.
	instruction of the second of t	m: 21° 46′.54 <b>N</b> .,	91°23′.59E.
	Osar omono to:	21° 46′.74N.,	91°23′.58E.
	2-April 2023		
Replace	with 🙉 🖽	Wk 22° 12'.42N.,	91° 43'.83E.
	wk with 49 1	Wk 22° 15'.55N.,	91° 44'.31E.

Charts affected - BN 1501, BN 3001 (INT 7427), BN 3507, BN 7510 (INT 7428), BN 25001, BN 25002, BN 30002, BN 35001 (INT 7425), BN 70001 (WGS84 DATUM)

- 2. BNHOC notice no 33(T)/2016, 32(T)/2019, 01(T)/2020, 11(T)/2020 & 07/2021 be treated as cancelled.
- All ships are requested to incorporate necessary corrections on above-mentioned charts and navigate accordingly.

M MINHAZ UDDIN Captain BN Commanding Officer

Distribution:

External:

Action:

BN Chief Hydrographer

- With request to circulate among the ships under your command.

Information (Not as per seniority):

Directorate of Naval Operations

Directorate of Hydrography

Bv E-mail

Commander Chattogram Naval Area

Commander Dhaka Naval Area

Commander Khulna Naval Area

Commander BN Fleet

Commander Submarine

- By E-mail (With request to circulate among the ships under respective command)

Commander	Flotil	la M	loct
Commander	FIOU	ia v	vest

Commodore Naval Aviation

Commodore SWADS Command

Coast Guard Headquarters
Directorate of Operations
Agargaon Admin Area
Sher-e-Bangla Nagar, Dhaka-1207

Chairman, Chattogram Port Authority

Chairman, Mongla Port Authority

Chairman, Payra Port Authority

Managing Director Bangladesh Shipping Corporation BSC Bhaban, Chattogram

Principal Officer, Mercantile Marine Office CGO Building, Agrabad, Chattogram

Deputy Conservator Chattogram Port Authority

Joint Director, BIWTA Terminal Bhaban, Feringhee Bazar Bridge Ghat Chattogram

Deputy General Manager, BIWTC Sadarghat, Chattogram

The United Kingdom Hydrographic Office Admiralty Way, Taunton, Somerset TA1 2DN, United Kingdom

- By E-mail (With request to circulate among the ships under respective command)

- By E-mail (With request to circulate among all BCG ships)

- By E-mail

- By E-mail (With request to circulate among the maritime organization/agencies)

- By E-mail