

Bangladesh Navy
Hydrographic and Oceanographic Centre
New Mooring, Chattogram
www.bnhoc.navy.mil.bd

Tel: 02333342500-30 ext 2420
E-mail: bnhoc@navy.mil.bd

06 Ashwin 1430

21 September 2023

23.02.1528.913.55.157.23. 849


BNHOC NOTICE NO 17/2023



References:


- A. BNHOC notice no 12(T)/2021 dated 10 March 2021.
- B. BNHOC notice no 17(T)/2021 dated 30 April 2021.
- C. BNHOC notice no 31(T)/2021 dated 18 July 2021.
- D. BNHOC notice no 12(T)/2022 dated 20 March 2022.
- E. BNHOC notice no 22(T)/2022 dated 26 May 2022.
- F. CPA letter no 18.04.0000.732.26.213.14.391 dated 19 April 2022 (Not to all).
- G. CPA Circular 02/2023 dated 17 January 2023 (Not to all).
- H. BNS SHAIBAL letter no 23.02.1528.431.37.162.23.1170 dated 30 March 2023 (Not to all).
- J. BNHOC notice no 05/2023 dated 02 April 2023.


1. Following **Permanent Notice to Mariners is hereby promulgated:**


Delete  22° 07'.98N., 91° 30'.16E

 22° 08'.54N., 91° 47'.39E

 22° 16'.12N., 91° 44'.80E
 LFI. 6s
Close of above.


 F.I.R. 6s
R MV Fulltala-1
Close of above.


 PA 22° 03'.50N., 91° 36'.94E

 PA 21° 58'.93N., 91° 21'.93E




 21° 57'.99N., 91° 21'.94E

Insert  22° 07'.98N., 91° 30'.17E

 22° 03'.45N., 91° 36'.96E

 F.I.R. 6s
R MV Fulltala-1
Close of above.


 Wks
Obstn 22° 11'.02N., 91° 23'.24E

Insert		Obstrn	21° 58'.62N., 91° 21'.27E
		Obstrn	21° 59'.79N., 91° 21'.64E
Move		from:	22° 05'.81N., 91° 31'.48E.
		to:	22° 05'.71N., 91° 31'.45E.

Charts affected – BN 3001 (INT 7427), BN 3507, BN 7509, BN 7510 (INT 7428), BN 25002, BN 30002, BN 35001 (INT 7425), BN 70001 [WGS 84 DATUM]

2. BNHOC Notice No 12(T)/2021 dated 10 March 2021, 17(T)/2021 dated 30 April 2021, 31(T)/2021 dated 18 July 2021, 12(T)/2022 dated 20 March 2022 & 22(T)/2022 dated 26 May 2022 be treated as cancelled.

3. All ships are requested to incorporate necessary corrections on above-mentioned charts and navigate with caution.



M HABIB UL ALAM
Captain BN
Commanding Officer

Distribution:

External:

Action:

BN Chief Hydrographer - With request to circulate among the ships under command.

Information (**Not as per seniority**):

Directorate of Naval Operations

Directorate of Hydrography

Commander Chattogram Naval Area

Commander Dhaka Naval Area

Commander Khulna Naval Area

Commander BN Fleet

Commodore Naval Aviation

Commander Submarine

Commander Flotilla West

Commodore SWADS Command

- By E-mail

- By E-mail (With request to circulate among the ships under respective command)

Coast Guard Headquarters
Directorate of Operations
Agargaon Admin Area
Sher-e-Bangla Nagar, Dhaka-1207

- By E-mail (With request to circulate among all BCG ships)

Chairman, Chattogram Port Authority

Chairman, Mongla Port Authority

- By E-mail

Chairman, Payra Port Authority

Managing Director
Bangladesh Shipping Corporation
BSC Bhaban, Chattogram

- By E-mail

Principal Officer, Mercantile Marine Office
CGO Building, Agrabad, Chattogram

- By E-mail (With request to circulate among the maritime organization/agencies)

Deputy Conservator
Chattogram Port Authority

Joint Director, BIWTA
Terminal Bhaban, Feringhee Bazar
Bridge Ghat Chattogram

- By E-mail

Deputy General Manager, BIWTC
Sadarghat, Chattogram

The United Kingdom Hydrographic Office
Admiralty Way, Taunton, Somerset
TA1 2DN, United Kingdom