Bangladesh Navy Hydrographic and Oceanographic Centre New Mooring, Chattogram www.bnhoc.navy.mil.bd

Tel: 01769-722420

E-mail: bnhoc@navy.mil.bd

29 Jaistho 1431

23.02.1528.913.55.157.24. 559

17 June 2024

BNHOC NOTICE NO 24(T)/2024

References:

- A. MPA Circular No.15/2024 (Not to all).
- B. BNHOC Notice No 08/2021 dated 15 February 2021.
- C. BNHOC Notice No 23(T)/2024 dated 05 June 2024.
- 1. Following **Temporary** Notice to Mariners is hereby promulgated:

	Buoy	Latitude	Longitude	Remark
R R	FI.R.6s B-6	21° 31′.07N	89° 27′.57E	Missing
I R	FI(3)R. 15s B-10	21° 35′.93N	89° 26′.93E	Missing

Charts affected: BN 5001 (INT 7426), BN 25001, BN 30001, BN 35001 (INT 7425), [WGS84 DATUM]

2. All ships are requested to incorporate necessary correction on above-mentioned charts and navigate with caution.

REZAUR RAHMAN Captain BN

Commanding Officer

Distribution:

External:

Action:

BN Chief Hydrographer - With request to circulate among the ships under your command.

Information (Not as per seniority):

Directorate of Naval Operations

- By E-mail.

Directorate of Hydrography

	Commander Chattogram Naval Area			
Commander Khulna Naval Area				
Commander BN Fleet				
Commander Dhaka Naval Area				
	Commander Flotilla West			
	Commander Submarine	- By E-mail (With request to circulate among the ships under respective command).		
	Commodore Naval Aviation			
	Commodore SWADS Command		w.	
	Coast Guard Headquarters Directorate of Operations	*		
	Chairman, Chattogram Port Authority			
	Chairman, Payra Port Authority			
	Chairman, Mongla Port Authority	- By E-mail.		
	Managing Director Bangladesh Shipping Corporation			
Principal Officer, Mercantile Marine Office - By E-mail (With request to circulate among the				
	Joint Director, BIWTA, Khulna	maritime organizations/agencies).		
	Deputy General Manager, BIWTC, Kh	ılna - By E-mail.		
	The United Kingdom Hydrographic Of	ce		
		ı		