

Bangladesh Navy  
Hydrographic and Oceanographic Centre  
New Mooring, Chattogram  
www.bnhoc.navy.mil.bd

Mobile: 01769722420  
E-mail: bnhoc@navy.mil.bd

25 Magh 1432

23.02.1528.913.55.157.26.126

08 February 2026

**BNHOC NOTICE NO 04(T)/2026**

References:

A. MPA Circular No 02/2026 dated 12 January 2026 (Not to all).  
B. BNHOC Notice No 33(T)/2025 dated 24 September 2025.

1. Following **Temporary Notice** to Mariners is hereby promulgated:

Insert	Position	Remarks
315°-135° ---<--->---	(a) 21°27.18'N 089°32.49'E to (b) 21°31.52'N 089°27.79'E	
354°-174° ---<--->---	(b) 21°31.52'N 089°27.79'E to (c) 21°36.58'N 089°27.19'E	
006°-186° ---<--->---	(c) 21°36.58'N 089°27.19'E to (d) 21°38.02'N 089°27.34'E	
019°-199° ---<--->---	(d) 21°38.02'N 089°27.34'E to (e) 21°41.04'N 089°28.44'E	Recommended track
003°-183° ---<--->---	(e) 21°41.04'N 089°28.44'E to (f) 21°47.02'N 089°28.77'E	
047°-227° ---<--->---	(f) 21°47.02'N 089°28.77'E to (g) 21°48.66'N 089°30.64'E	

**Charts affected: BN 5001(INT 7426), BN 25001, BN 30001, BN 35001 (INT 7425)  
[WGS 84 DATUM]**

2. BNHOC Notice No 33(T)/2025 be treated as cancelled.  
3. All ships are requested to incorporate necessary corrections for the above-mentioned charts and navigate accordingly.

  
REZAUR RAHMAN  
Captain BN  
Commanding Officer

Distribution:

External:

Action:

BN Chief Hydrographer - With request to circulate among the ships under your command.

