

IMM

BNHOC
New Mooring
Chittagong
www.bnhoc.navy.mil.bd

Tel: 740391-9 ext 4170
E-mail: bnhoc@navy.mil.bd

23.02.1528.340.55.157.18. 264

28 May 18

BNHOC NOTICE NO 08(T)/2018

Ref:

A. COMBAN ltr no 23.02.1528.400.37.405.18.1968 dated 23 May 2018.

1. An **Obstn** area has been established, bounded by the following positions:



21°35'·52N, 091°49'·24E.
21°35'·66N, 091°49'·24E.
21°35'·66N, 091°49'·61E.
21°35'·52N, 091°49'·61E.

2. Mariners are advised to navigate with caution in the vicinity.
(WGS84 DATUM)

Charts Affected: BN 3505, BN 7511 (INT 7429), BN 25002, BN 35001 (INT 7425) & BN SPL-18

3. All BN ships are requested to incorporate necessary correction on above-mentioned charts and navigate accordingly.

M JASHIM UDDIN
Instr Captain BN
Officer in Charge

o/c
W. C. M. N. H. K.
o/c-Pub

Distr:

Extl:

Act:

The Commanding Officer/Officer In - charge
BNS/BNT -----

(All ships/crafts under COMCHIT)

Info:

Dte of Naval Operations

Dte of Hydrography

Commander Chittagong Naval Area

Commander BN Fleet

Administrative Authority Dhaka



With request to circulate to ships under
respective Command/Org

COMFLOT West

Commodore SWADS Command

Commander Submarine

Commodore Naval Aviation

CG Force Headquarters, Dte of Operations
Agargaon Admin Area, Sher-e-Bangla Nagar
Dhaka 1207

With request to circulate to ships under
respective Command/Org

Chairman, Chittagong Port Authority
Chittagong

Chairman, Payra Port Authority
Al-Amin Millennium Tower (7 Level)
75-76 Kakrail, Dhaka - 1000

Chairman, Mongla Port Authority
Digraj, Mongla, Bagerhat

Principal Officer, Mercantile Main Department
CGO Building, Agrabad, Chittagong

Managing Director
Bangladesh Shipping Corporation
BSC Bhaban, Chittagong

Deputy Conservator
Chittagong Port Authority, Chittagong

Joint Director, BIWTA
Terminal Bhaban, Feringhee Bazar
Bridge Ghat Chittagong

Deputy General Manager, BIWTC
Sadarghat, Chittagong

The United Kingdom Hydrographic Office
Admiralty Way, Taunton, Somerset
TA1 2DN, UK

- By e-mail.