

23.02.1528.913.55.157.19. 681



























11 November 2019

**BNHOC NOTICE NO 43/2019**

Reference:

A. CPA Circular no 46/2019 dated 01 October 2019 (Not to all).

1. Following **PERMANENT** Notice to Mariners are hereby promulgated:

Insert		22° 12'.89N, 091° 46'.25E	Insert		22° 16'.00N, 091° 45'.10E
		22° 13'.35N, 091° 45'.70E			22° 16'.00N, 091° 42'.70E
		22° 13'.55N, 091° 46'.20E			22° 16'.40N, 091° 44'.50E
		22° 14'.20N, 091° 44'.70E			22° 16'.47N, 091° 43'.38E
		22° 14'.10N, 091° 45'.76E			22° 16'.79N, 091° 43'.90E
		22° 14'.46N, 091° 45'.12E			22° 17'.10N, 091° 44'.45E
		22° 14'.68N, 091° 44'.20E			22° 16'.68N, 091° 42'.70E
		22° 15'.00N, 091° 44'.50E			22° 18'.30N, 091° 44'.10E
		22° 15'.05N, 091° 45'.46E			22° 17'.42N, 091° 42'.63E
		22° 15'.00N, 091° 43'.60E			22° 16'.90N, 091° 42'.16E
		22° 15'.52N, 091° 44'.75E			22° 18'.50N, 091° 43'.50E
		22° 15'.74N, 091° 43'.45E			22° 18'.79N, 091° 43'.00E
		22° 16'.00N, 091° 44'.00E			22° 19'.30N, 091° 43'.59E

**Charts affected – BN-3001(INT 7427) [WGS 84 DATUM]**

2. For detail information on anchorage berth mariners are advised to contract Chattogram Port Authority.

3. All BN ships are requested to incorporate necessary correction on above-mentioned charts and navigate accordingly.

  
SHEIKH FIROZ AHMED  
Captain BN  
Commanding Officer

Distribution:

External:

Action:

The Commanding Officer

BNS \_\_\_\_\_  
(All ships under Bangladesh Navy Chief Hydrographer)

Information:

Directorate of Naval Operations

Directorate of Hydrography

Commander Chattogram Naval Area  
 Commander BN Fleet  
 Commander Khulna Naval Area  
 Commander Submarine  
 Administrative Authority Dhaka  
 Commodore SWADS Command  
 Commander Flotilla West  
 Commodore Naval Aviation  
 Coast Guard Force Headquarters  
 Directorate of Operations  
 Agargaon Admin Area  
 Sher-e-Bangla Nagar, Dhaka-1207  
 Chairman, Chattogram Port Authority  
 Chairman, Payra Port Authority,  
 Al-Amin Millennium Tower (7 Level)  
 75-76 Kakrail, Dhaka - 1000  
 Chairman, Mongla Port Authority  
 Principal Officer, Mercantile Marine Office  
 CGO Building, Agrabad, Chattogram  
 Managing Director  
 Bangladesh Shipping Corporation  
 BSC Bhaban, Chattogram  
 Deputy Conservator  
 Chattogram Port Authority, Chattogram  
 Joint Director, BIWTA  
 Terminal Bhaban, Feringhee Bazar  
 Bridge Ghat Chattogram  
 Deputy General Manager, BIWTC  
 Sadarghat, Chattogram

- With request to circulate to ships under respective Command/Organizations.

- With request to circulate amongst the maritime Organization/Agencies .

The United Kingdom Hydrographic Office  
 Admiralty Way, Taunton, Somerset  
 TA1 2DN, United Kingdom

- By E-mail.

Internal:

Information:

Bangladesh Navy  
 Chief Hydrographer